

Case Study – Refurbishment of ‘Danny’ Dino 3

Date: Feb – April 2014

Plant No. VE 007

Reason for Works :

- As one of our oldest units and with over 4500 hours it was necessary to carry out a full refurbishment on this unit
- Excessive rust patches
- Bring logo scheme in line with new company brand
- Too much play in tipping and arm bearings
- Preventative future maintenance



Works carried out :

- Full arm refurb
- Complete skip and lid refurb
- New turbine bearings and belts
- Electrical system rectified
- Replaced all hydraulic rams
- Replaced hydraulic pipework
- Replaced 2 turbine belts
- Complete re-spray and new livery to bring in line with company brand
- Replaced halogen bulbs with full LED working lights and hazard lighting
- Full service



Report Author: Chris Cunningham

Signed: _____