



**Case Study – Refurbishment of Dump-Ex**

**Date: March – June 2013**

**Plant No. VE 003**

**Reason for Works :**

- Excessive rust patches
- Articulation bearing play
- Bring into new company colour scheme with new logo
- Wear & tear



**Works carried out :**

- Total strip down
- Skip shot blast
- Powder coat & 2 coat spray
- Full engine service
- New vacuum seals
- New H&S decals
- New company logo



**Report Author: Chris Cunningham**

**Signed: \_\_\_\_\_**